11 11

1 号楼 (6F)

窗框安装完成90%,外墙保温完成16%



2 号楼 (8+1F)

外墙保温完成98%,涂料完成95%, 室内精装修完成55%



3 号楼 (15F)

外立面保温完成98%,外墙涂料完成 65%,精装修完成26%



4 号楼 (6F)

窗框安装完成90%,保温完成12%



5 号楼(8+1F)

外墙保温完成,外墙涂料完成95%, 室内精装完成60%



6 号楼(8+1F)

外墙保温完成,外墙涂料完成95%, 室内精装完成65%



7 号楼 (16F)

外墙保温完成98%,外墙涂料完成85%, 室内精装修完成45%



8 号楼 (6F)

室内砌体、抹灰完成, 窗框安装85%



9 号楼(8+1F)

外墙保温完成97%,外墙涂料完成76%, 室内精装完成41%



10 号楼 (8+1F)

外墙保温完成,涂料完成95%,精装 完成45%



11 号楼(16F)

外墙保温完成80%,涂料施工20%



12 号楼 (8+1F)

外墙保温完成97%,涂料完成75%, 精装修包电梯门套完成



13 号楼 (8+1F)

外墙保温完成97%,涂料完成71%, 精装包电梯门套完成



14 号楼(15F)

室内砌体、抹灰完成,外墙保温完成50%,室内精装修施工16%



15 号楼 (8+1F)

外立面保温完成97%,涂料完成71%, 室内精装包电梯门套完成



16 号楼 (8+1F)

外立面保温完成9%,外墙涂料完成20% 精装修包电梯门套完成



17 号楼(16F)

外墙保温完成10%



18 号楼(16F)

室内精装完成11%



19 号楼(16F)

外保温完成81%,涂料完成20%。室内 精装修完成35%



20 号楼 (15F)

窗框安装完成,外墙保温完成8%,外墙涂料完成20%。室内精装完成15%



21 号楼 (15F)

室内砌体、抹灰完成,地辐热保护层 浇筑完成



室外

车库顶板防水及保护层施工完成98%, 室外回填土完成51%,小市政施工42%, 景观完成20%



地下

地库二构及抹灰施工完成,一遍腻子 完成85%,顶棚涂料完成71%,地坪浇 筑完成60%,桥架安装62%,消防风管 安装14%

